



### General Details

Assessor	Ben Letschka
Assessment Date	19/11/2019
Assigned Reviewer	Gemma Leigh
Next Review Date	23/02/2021

Signed Off By	Gemma Leigh
Signed Off On	16/02/2020

Operation Assessed	Hardcourts
--------------------	------------

### Associated with specific area

- Registrar and Secretary
- Sport and Recreation Service
- Facilities

### Description of work area and/or activity assessed

USE IN CONJUNCTION WITH GENERIC FACILITY RISK ASSESSMENT

Falmer/Eastbourne: Outdoor hard courts, non roofed with close by trees. Floodlit. Tennis, netball, futsal.

### Overall Current Risk

Low



### Persons Affected

- Children (<16)
- Contractors
- New mothers
- Others
- Persons with disabilities
- Pregnant people
- Staff
- Students
- Visitors
- Young persons (16-17)

Current Rating	Hazard Information	Task Status
<div>Low</div> <div> <div></div> <div></div> <div></div> <div></div> <div></div> </div>	<div> <div></div> <b>Slip / Trip</b> </div> <div> Slip on wet leaves which fall from the trees. Moss build up on ground. Seceptible to freezing temperatures. </div>	<div> <div>0</div> <div>0</div> <div>0</div> </div>
	Measures Currently in place to prevent risk of injury	
	Regular sweep by EFM. Monitoring and reporting to EFM to clear if needed. Inspection prior to use in cold weather.	

Potential Rating	Additional Controls Required
<div>Low</div> <div> <div></div> <div></div> <div></div> <div></div> <div></div> </div>	<div> <b>No Remedial Actions Entered</b> </div> <div> If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them. </div>

Current Rating	Hazard Information	Task Status
<div>Low</div> <div> <div></div> <div></div> <div></div> <div></div> <div></div> </div>	<div> <div></div> <b>Lifting equipment</b> </div> <div> Drop heavy post on foot. Injure back from carrying heavy posts. trip from getting tangled in net. </div>	<div> <div>0</div> <div>0</div> <div>0</div> </div>
	Measures Currently in place to prevent risk of injury	
	Training given to anyone expected to set up and take down the tennis nets and posts. This will ensure they know a safe way to do it. There is a trolley which the posts and nets can go on to transport, so carrying the load does not need to be manual.  Encourage staff members to report any feedback relating to setting up and taking down tennis nets and posts.	

Potential Rating	Additional Controls Required
<div>Low</div> <div> <div></div> <div></div> <div></div> <div></div> <div></div> </div>	<div> <b>No Remedial Actions Entered</b> </div> <div> If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them. </div>

Current Rating	Hazard Information	Task Status
<div>Low</div> <div> <div></div> <div></div> <div></div> <div></div> <div></div> </div>	<div> <div></div> <b>Slip / Trip</b> </div> <div> Trip on erected post cover after tennis posts have been taken out. </div>	<div> <div>0</div> <div>0</div> <div>0</div> </div>
	Measures Currently in place to prevent risk of injury	
	Staff training to ensure that post covers are flattened when a post is not currently up. Regular Duty Officer checks to look out for hazards.	

Potential Rating	Additional Controls Required
<div>Low</div> <div> <div></div> <div></div> <div></div> <div></div> <div></div> </div>	<div> <b>No Remedial Actions Entered</b> </div> <div> If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them. </div>

--